## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	(pyrometer) and ((hand same held) or portable) and (cable same (hand same held) same portable same optical)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:10
L2	1433	(radiant same energy same meter)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:11
L3	55	(radiant same energy same meter) and (cables same optical)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:11
L4	0	(radiant same energy same meter) and (cables same optical) and (explode explosion explodes)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:15
L5	287	(pyrometer) and (explosion)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:23
L6	8	(pyrometer) and (explosion) and wireless	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:23

L7	53	¿ (	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:24
L8	0	(PROFIBUS OR HART) and	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:25
L9	2	; \	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/02/19 14:25

2/19/08 2:26:19 PM

C:\ Documents and Settings\ tstevens\ My Documents\ EAST\ Workspaces\ default.wsp